Oil Field Environmental Incident Summary

Responsible Party: STATOIL OIL & GAS LP
Well Operator: STATOIL OIL & GAS LP
Well Name: GREENSTEIN 30-31 3TFH

Field Name: CAMP Well File #: 24548

Date Incident: 8/1/2015 Time Incident: 15:56 Facility ID Number:

County: MCKENZIE Twp: 152 Rna: 101 Sec: 30 Qtr: LO T1

Location Description:

Submitted By: Derrick McBride Received By:

Contact Person: Derrick McBride

6300 BRIDGE POINT PKY, BLDG 2

SUITE 500

AUSTIN, TX 78730

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 150 Barrels 150 Barrels 150 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 9/1/2016 Clean Up Concluded: 8/2/2015

Risk Evaluation:

None all product was contained within the tank battery lined containment

Areal Extent:

Potential Environmental Impacts:

None all product was contained within the tank battery lined containment

Action Taken or Planned:

Gravel within the tank battery area will be remediated Remove and replace 6" connection gasket Increase the inspection frequency of gaskets

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 8/3/2015 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained on location according to the report. NDIC retains oversight.